Appendix A – Site Photos

GYY Airport Appendices



Photo 49. DP13. Facing east. October 25, 2022.



Photo 51. DP13. Facing west. October 25, 2022.



Photo 50. DP13. Facing south. October 25, 2022.



Photo 52. DP13. Soil profile. October 25, 2022.



Photo 53. DP13. Soil pit. October 25, 2022.



Photo 55. DP14. Facing east. October 25, 2022.



Photo 54. DP14. Facing north. October 25, 2022.



Photo 56. DP14. Facing south. October 25, 2022.



Photo 57. DP14. Facing west. October 25, 2022.



Photo 59. DP14. Soil pit October 25, 2022.



Photo 58. DP14. Soil profile. October 25, 2022.



Photo 60. DP15. Facing north. October 25, 2022.



Photo 61. DP15. Facing east. October 25, 2022.



Photo 63. DP15. Facing west. October 25, 2022.



Photo 62. DP15. Facing south. October 25, 2022.



Photo 64. DP15. Soil profile October 25, 2022.



Photo 65. DP15. Soil pit. October 25, 2022.



Photo 67. DP16. Facing east. October 25, 2022.



Photo 66. DP16. Facing north. October 25, 2022.



Photo 68. DP16. Facing south October 25, 2022.



Photo 69. DP16. Facing west. October 25, 2022.



Photo 71. DP16. Soil pit. October 25, 2022.



Photo 70. DP16. Soil profile. October 25, 2022.



Photo 72. DP17. Facing north. October 25, 2022.



Photo 73. DP17. Facing east. October 25, 2022.



Photo 75. DP17. Facing west. October 25, 2022.



Photo 74. DP17. Facing south. October 25, 2022.



Photo 76. DP17. Soil profile October 25, 2022.

Stantec No. 238102012



Photo 77. DP18. Facing north. October 25, 2022.



Photo 79. DP18. Facing south. October 25, 2022.



Photo 78. DP18. Facing east. October 25, 2022.



Photo 80. DP18. Facing west October 25, 2022.



Photo 81. DP18. Soil profile. October 25, 2022.



Photo 83. DP19. Facing north. October 25, 2022.



Photo 82. DP18. Soil pit. October 25, 2022.



Photo 84. DP19. Facing east October 25, 2022.



Photo 85. DP19. Facing south. October 25, 2022.



Photo 87. DP19. Ground. October 25, 2022.



Photo 86. DP19. Facing west. October 25, 2022.



Photo 88. PS01. Facing north. October 25, 2022.



Photo 89. PS01. Facing east. October 25, 2022.



Photo 91. PS01. Facing west. October 25, 2022.



Photo 90. PS01. Facing south. October 25, 2022.



Photo 92. PS02. Facing north October 25, 2022.



Photo 93. PS02. Facing east. October 25, 2022.



Photo 95. PS02. Facing west. October 25, 2022.




Photo 94. PS02. Facing south. October 25, 2022.



Photo 96. PS03. Facing north October 25, 2022.



Photo 97. PS03. Facing east. October 25, 2022.



Photo 99. PS03. Facing west. October 25, 2022.



Photo 98. PS03. Facing south. October 25, 2022.



Photo 100. PS04. Facing north October 25, 2022.



Photo 101. PS04. Facing east. October 25, 2022.



Photo 103. PS04. Facing west. October 25, 2022.



Photo 102. PS04. Facing south. October 25, 2022.



Photo 104. PS05. Facing north. October 25, 2022.



Photo 105. PS05. Facing east. October 25, 2022.



Photo 107. Facing west. October 25, 2022.



Photo 106. PS05. Facing south. October 25, 2022.



Photo 108. PS06. Facing north. October 25, 2022.



Photo 109. PS06. Facing east October 25, 2022.



Photo 111. PS06. Facing west. October 25, 2022.



Photo 110. PS06. Facing south. October 25, 2022.



Photo 112. PS07. Facing north. October 25, 2022.

Stantec No. 238102012



Photo 113. PS07. Facing east October 25, 2022.



Photo 115. PS07. Facing west. October 25, 2022.



Photo 114. PS07. Facing south. October 25, 2022.



Photo 116. Wetland 10. October 25, 2022.

NGC Corporation Lake County, Indiana